


WIRING DIAGRAM FOR GREDDY BOOST CUT CONTROLER AND SPEED CUT DEFENCE

SAMPLE



+B 12 VOLT IGNITION
- GROUND SOURCE

SPD SPEED SENSOR INPUT

B/C BOOST CUT INPUT

RPM RPM PULSE SOURCE